

Consider the reliability equation

Reliability = f (stress, parameters, environment,
materials, usage, ...)

left side

measure
reliability

right side

manage process inputs,
support reliability in design

Where should the emphasis be?